

TEST REPORT

COMPETITORS PACKERS RETURNED TO RIPE FOR REBUILD

ARE YOU EXPERIENCING THE SAME ISSUES?

CONTACT US TODAY



REPLACEMENT INFLATABLE PACKERS AND ELEMENTS PTY LTD

Contact: John Misson

Phone: 08 9475 0700

Mobile: 0400 346 687

Email: packers@ripe-packers.com

Address: 29 Wheeler Street, Belmont WA 6104

PQ PACKER Ø80 (115RM—S1017 / 10-08-11)

OUT OF SERVICE TAG: No Tag

Embossing: 115RM—S1017 Date: 10-08-11

Comments: Failed vulcanising under ferrules on initial inflation.



Ø80 SLIDING END - 7K PACKER (47RB4070 / 17-3-03)

OUT OF SERVICE TAG: No Tag

Embossing: 47RB4070 Date: AGE 17/03/03

Comments:



HQ PACKER Ø60 (88LT-S1013 / 10-07-19)

OUT OF SERVICE TAG:

Defects: Seal Fail/O-ring

Name: Johnson

Date: 04-05-2020 (13:00)

Embossing: 88LT-S1013 Date: 10-07-19

Comments: Failed vulcanising under ferrules on initial inflation.



HQ PACKER Ø60 (87LT-S1013 / 10-07-19)

OUT OF SERVICE TAG:


Defects: Swollen

Name: Dan

Date: 01-04-2020

Embossing: 87LT-S1013 Date: 10-07-19

Comments: Failed on third inflation at 700psi in Ø96mm hole/pipe. Failed vulcanising under ferrule.
First 2 inflations completed at 1000psi in a Ø96mm hole/pipe.



HQ PACKER Ø60 (86LT S1013 / 08-07-19)

OUT OF SERVICE TAG:

Defects: Leaking from O Ring / Thread to be checked

Name: Dan

Date: 01-04-2020

Embossing: 86LT S1013 Date: 08-07-19

Comments: Failed on initial inflation. Failed vulcanising under ferrule

